


Thermometer/hygrometer monitors temperature and humidity.



Melted ice used for cooling oxygen is drained from compartment through convenient valve.

Clear polycarbonate panel resists scratches and discoloration.